(19) World Intellectual Property Organization

International Bureau



(43) International Publication Date 16 June 2005 (16.06.2005)

PCT

(10) International Publication Number WO 2005/054619 A1

(51) International Patent Classification7: 9/52, 9/01

E06B 9/24,

(21) International Application Number:

PCT/AU2004/001697

(22) International Filing Date: 2 December 2004 (02.12.2004)

(25) Filing Language:

English

(26) Publication Language:

English

(30) Priority Data:

2003906662

2 December 2003 (02.12.2003)

(71) Applicant (for all designated States except US): BRAD-NAM'S WINDOWS & DOORS PTY LTD [AU/AU]; Links Avenue North, Eagle Farm, Queensland 4009 (AU).

(72) Inventor; and

(75) Inventor/Applicant (for US only): HEADS, Frank, Xavier [AU/AU]; 10 Mellifont Street, Banyo, Queensland


(81) Designated States (unless otherwise indicated, for every kind of national protection available): AE, AG, AL, AM, AT, AU, AZ, BA, BB, BG, BR, BW, BY, BZ, CA, CH, CN, CO, CR, CU, CZ, DE, DK, DM, DZ, EC, EE, EG, ES, FI, GB, GD, GE, GH, GM, HR, HU, ID, IL, IN, IS, JP, KE, KG, KP, KR, KZ, LC, LK, LR, LS, LT, LU, LV, MA, MD, MG, MK, MN, MW, MX, MZ, NA, NI, NO, NZ, OM, PG, PH, PL, PT, RO, RU, SC, SD, SE, SG, SK, SL, SY, TJ, TM, TN, TR, TT, TZ, UA, UG, US, UZ, VC, VN, YU, ZA, ZM, ZW.

(84) Designated States (unless otherwise indicated, for every kind of regional protection available): ARIPO (BW, GH, GM, KE, LS, MW, MZ, NA, SD, SL, SZ, TZ, UG, ZM, ZW), Eurasian (AM, AZ, BY, KG, KZ, MD, RU, TJ, TM), European (AT, BE, BG, CH, CY, CZ, DE, DK, EE, ES, FI, FR, GB, GR, HU, IE, IS, IT, LT, LU, MC, NL, PL, PT, RO, SE, SI, SK, TR), OAPI (BF, BJ, CF, CG, CI, CM, GA, GN, GQ, GW, ML, MR, NE, SN, TD, TG).

Published:

- with international search report
- with amended claims and statement

For two-letter codes and other abbreviations, refer to the "Guid-



frame (15) in an improved manner and without requiring rivets or welding by providing a recess (16) in the edge of the panel and a rib (18) in the peripheral frame which passes into the recess to hold the parts together. When the security door/window is assembled, the panel is trapped and cannot slide out of engagement with the frame.



